

Northumberland Dock Road, Wallsend, Tyne & Wear, NE28 0QD

Tel: 0191 2968366 Fax: 0191 2968560 [www.nwss-labs.co.uk](http://www.nwss-labs.co.uk)

**Customer:** Mr Simon Edwards  
SJ3 Outdoors Ltd

**Address:** Fairhaven Gardens School Road  
South Walsham Norwich

**Contract Reference:** SJ3\_OUT-02938  
**Contract Description:** Lake Water Testing  
**Project Manager:** Nicola Hewison

**Postcode:** NR13 6DZ

**Lab Number:** 3040024

**Date & Time Taken:** 28/08/24 12:00

**Sample Name:** South Walsham Broad- Boat House

**Date Received:** 03/09/24

**Date Started:** 03/09/24

Lake Water - This sample was deviating for micro analysis and as a result the test result(s) may be compromised. This sample has determinands that have exceeded their stability time.

**Sample Point:**

**Collected From:**

PARAMETER	RESULTS	METHOD	SITE
algae	43300 /1ml	BI01	CD
dominant species	ANABAENA	BI01	CD
sub-dominant species	DESMODESMUS	BI01	CD
enterococci (confirmed)	0 /100ml	HY-004	CD
enterococci (presumptive)	0 /100ml	HY-004	CD
E.coli	1 /100ml	HY-073	CD

Please find below the list of incident report references relating to this sample. Each separate incident report detailed must be reviewed with the main analytical report. Please Contact the Customer Team if you have queries regarding any of these reports.

3040024\_28/8\_\_39

3040024\_28/8\_\_50

**Authorised By:**



Carmen Sanchez  
Laboratory Team  
Leader

Under the authority of  
Ian Barnabas  
Head of Laboratories and Sampling

This report was compiled by the Customer Department

Opinions and interpretations expressed herein are outside the scope of UKAS accreditation

**Date of issue:** 18/09/24

Results relate only to the items tested and are reported without Uncertainty of Measurement (UOM) applied. UOM data is available upon request.

Customer provided data is highlighted in grey. Customer provided data may affect validity of results. Samples are analysed and reported 'as received'.

Tests marked HN analysed at Howdon Laboratory, Northumberland Dock Road, Wallsend, Tyne & Wear, NE28 0QD

Tests marked HY analysed at Horsley Laboratory, Horsley, Newcastle upon Tyne, NE15 0PE

Tests marked CD analysed at Chelmsford Laboratory, Middlemead, South Hanningfield, Chelmsford, Essex, CM3 8HS

Tests marked OS analysed On-Site Tests marked SU analysed by subcontractor